DOCKETFILE COPY ORIGINAL

BEFORE THE FEDERAL COMMUNICATIONS COMMISSION WASHINGTON, D.C. 20554

The state of the s
MAR 3 3 2003
FCC - MAILROOM

PETITION FOR RULE CHANGE

etitioner:)	
ale E. Reich)	RM DOCKET NUMBER
41 North Center St. eville Ohio 44273 - 9504)	

hanges Requested in Part's 2 - 90 - 95 - 97

Vith regards to the problems with the "Illegal Type" or "so Called" **Export CB /** Ham radios combinations ianufactured and sold throughout the United States I request the FCC to consider this "RM" rule making ?quest.

quipment manufactured within the 25 Mhz to 30 Mhz range must be "Type" accepted for only "Authorized" radio ervices, and shall not be sold or marketed to transmit outside the "Authorized" frequencys range in over the ounter sales! Each new manufactured radio shall bear a "Type" acceptance or "Type Approval" tag and ertificate. Each new radio shall bear a imbedded serial number unique to each radio. The Certificate attached each radio will give the current official business address of the final manufacture U.S. Based address for actory and/or importer of the radio.

he owners manual or any papers that come with the radio will not show how to make any modifications to CC regulations.

'he tag will also bear the wording to the effect that repairs must be made by only a authorized or certified factor tation. Because the Export CB / Ham radio operates on international frequencys below 30 Mhz it can only be ?pairedby licensed "Ham" operators or Commercial Radio Telephone [Of the Correct License Class] repair censees.

'the manufacture makes claim's that the radio can operate on CAP or MARS military frequencys. they must eek certification from that agency as well as the Commission,to make such operation legal.

'he Transmitter must be "Fixed on center of authorized frequency, unless a grant of Type Acceptance or Type approval is received from the commission. Most of the SSB export radio's VFO or Crystal VFO the transmitter arough the PLL frequency control computer. So on all non "ham" [Amateur Radio] equipment there is no need to ave the PLL or TXO have the ability to VFO between channels.

'the unit is NBFM it must comply with the maximum frequency deviation of no more than 2.5 kc Max. The sceiver must also comply with this new standard. In the Type acceptance of the radio it must be also have a actory seal for frequency and deviation controls to show if the radio can't be easily field modified. For the susiness user of Part 90 or [Like] services that are all ready licensed and "Grandfathered for this area this rule raking will exempt them from the new standards. The Export standard for the Illegal radio standard is 5kc to 6k ommon on radios tested in the past. This makes almost all the Illegal Export radios not even useable under pa 10 if they apply for a STA or Waver

Radio Shops, retail vendors, and sales agencies would be required to register under the ULS to seek a FCC cense to be a "Radio Transmitter Vendor" for marketing of Part 95 or 97 equipment. The registration and ertificate to the vendor would be "free" if retail vendor operations takes place and continues at the same locatic small renewal fee shall be charged to the applicant later! The WTB would make the fine detail rules for this

No. of Copies rec'd OFS
List ABODE
WTB

red licensing of the vendors of **sub** part in a public notice. Stores that exclusive only **sell** "Ham" or [Amateur Rap's] would be exempt from this requirement to license a retail store. Store listing on the FCC **web** would **als** it easy to fine original manufacture for authorized after market repairs, as well as "authorized" agents for purchases repairs! The normal business hours the manufacture and vendors must be posted on the FCC uls te for the manufactures of any equipment that is sold, manufactured, marketed, leased, or operated in the understand the states in the 25 Mhz to 30 Mhz Band.

VTB would be able to "tine tune" this requested "RM" under administrative rule changes and upon **posting** on the FCC public notices.

Thanks

Dale E.. Reich 141 North Center St.

Seville, Ohio 44273 - 9504

ak437@mail.acorn.net